

# HEZE MAOSHENG WOOD PRODUCTS CO., LTD. TEST REPORT

### **SCOPE OF WORK**

EN 1634-1:2014+A1:2018 TESTING ON SINGLE LEAF TIMBER DOOR WITH PARTICLE BOARD CORE, MODEL OF MS-001A

**REPORT NUMBER** 190920007SHF-001

**TEST DATE** 2019-11-11


**ISSUE DATE** 2019-11-27

PAGES

26

DOCUMENT CONTROL NUMBER

LFT-APAC-SHF-OP-10p (May 1, 2019) © 2019 INTERTEK





Issue Date: 2019-11-27

Intertek Report No.: 190920007SHF-001

#### **REPORT ISSUED TO**

HEZE MAOSHENG WOOD PRODUCTS CO., LTD. ZHUANGZHAI INDUSTRY ZONE, HEZE CITY SHANDONG PROVINCE, CHINA


### SECTION 1

SCOPE

Intertek has conducted an evaluation for HEZE MAOSHENG WOOD PRODUCTS CO., LTD. to determine the fire resistance characteristics of single leaf timber door with particle board core, model of MS-001A. This evaluation began on September 20, 2019 and was completed on November 22, 2019. The test was conducted on November 11, 2019.

The test was conducted in accordance with EN 1634-1:2014+A1:2018, Fire resistance and smoke control tests for door and shutter assemblies, openable windows and elements of building hardware – Part 1: Fire resistance test for door and shutter assemblies and openable windows.

This report does not constitute certification of this product nor an opinion or endorsement by this laboratory.



This report is for the exclusive use of Intertek's Client and is provided pursuant to the agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this report. Only the Client is authorized to permit copying or distribution of this report and then only in its entirety. Any use of the Intertek name or one of its marks for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test results in this report are relevant only to the sample(s) tested. This report by itself does not imply that the material, product, or service is or has ever been under an Intertek certification program.



Issue Date: 2019-11-27

Intertek Report No.: 190920007SHF-001

#### SECTION 2

#### SUMMARY OF TEST RESULTS

**Product Name:** Single leaf timber door with particle board core **Series/Model:** MS-001A

The test assemblies satisfied the performance requirements for the following periods:

PERFORMANCE CRITERIA	RESULTS				
	Sustained flaming	36 minutes			
Integrity	Gap gauge	36 minutes			
	Cotton pad	36 minutes			
Insulation		36 minutes			

The test was discontinued after a period of 36 minutes at the request of the sponsor.

### SECTION 3 TEST METHODS

The specimens were evaluated in accordance with the following:

**EN 1634-1:2014+A1:2018,** *Fire resistance and smoke control tests for door and shutter assemblies, openable windows and elements of building hardware – Part 1: Fire resistance test for door and shutter assemblies and openable windows* 

EN 1363-1:2012, Fire resistance tests – Part 1: General Requirements



Issue Date: 2019-11-27

Intertek Report No.: 190920007SHF-001

#### **SECTION 4**

### MATERIAL SOURCE/INSTALLATION

The specimens were randomly selected by Intertek B&C personnel Luke Lv at HEZE MAOSHENG WOOD PRODUCTS CO., LTD., located at ZHUANGZHAI INDUSTRY ZONE, HEZE CITY, SHANDONG PROVINCE, CHINA. The particle board core was witnessed during production and signed prior to shipment from September 23, 2019 to September 24, 2019. The doorsets were witnessed during production and signed prior to shipment from October 25, 2019 to October 26, 2019. The specimens were received at the Evaluation Center on November 01, 2019.

The subject test specimen is a traceable sample selected from the manufacturer's facility. Intertek selected the specimen and has verified the composition, manufacturing techniques and quality assurance procedures.

TESTED ASS		SCRIPTION				
	Туре	Single Leaf Single Action Swing Timber Door				
Door	Nominal size	1105mm wide by 2260mm high by 44mm thick				
2001	Core	44mm thick particle board, density of 600~620kg/m <sup>3</sup>				
	Lipping	4mm thick Sapelli solid wood, density of 685~705kg/m <sup>3</sup>				
Frame	Nominal size	1198mm wide by 2305mm high by 130mm deep				
Material		Sapelli solid wood, density of 685~705kg/m <sup>3</sup>				
	Hinge	Type: 2BB butt hinge; Model: DDSS001-4×3×3.0mm-SUS201; Quantity: 4				
CE Certified Hardware	Lock	Type: Mortise lock, Model: GBS31F SH6072; Backset: 60mm; Latch throw: 12mm; Latch bolt: Engaged; Dead bolt: Disengaged;				
Door closer		Model: D3023BW; Installation: Surface mounted standard installation with adjustable Power Size 3 on pull side of doorset.				
Intumescent seal		Model: YZ2504; Size: 25×4mm; Location: One strip mortise mounted around frame One strip mortise mounted around door leaf edge				

The sample ID number assigned by the test lab is S190920007SHF.001.



Issue Date: 2019-11-27

Intertek Report No.: 190920007SHF-001

The drawings of the single leaf timber door with particle board core, hardware and test wall construction can be found in Section 6, 7 and 8 respectively.

A comprehensive description of single leaf timber door with particle board core, model of MS-001A are maintained on Intertek file.

The test assembly was installed in a steel restraint frame. The test assembly was built into a concrete masonry unit partition, with fully mortared joints. The test assembly was to be moved in front of the furnace for the fire exposure. Prior to the commencement of the EN 1634-1 fire test, the specimen to be test was checked for operability in the fire test frame by operating from fully closed to fully open, for 25 cycles. The test measurement data was shown in Section 9.

The test door was mounted so as to open into the furnace chamber.

The nominal dimension of the test wall was 3 m high by 3 m wide.

After positioning the assembly frame over the furnace opening, the burners were ignited, and the timer was started. Temperatures within the furnace were monitored using thermocouples and the data was recorded. The burners were controlled to keep the furnace temperatures within the allowable limits specified in the test standards. After 5 minutes, the furnace pressure was adjusted so that the neutral plane was established at approximately 500 mm above notional floor level. Periodic observations were made of the surfaces of the test assembly during the fire resistance test.

Door deflection relative to the frame, where applicable, was monitored throughout the test. Position for measurement of deflection and unexposed temperature were presented in the drawing of Section 9.

### SECTION 5

#### TEST RESULTS

#### Integrity

The test assembly withstood the fire resistance test without passage of flame or gases hot enough to ignite cotton waste for 36 minutes. No through openings or penetrations were evident at this 36 minutes fire exposure portion of the test and the window bolt remained engaged to the strike. During this 36 minutes fire exposure period no significant flaming was observed on the unexposed face of the assembly.

After exposed to the fire for a period of 36 minutes, sustained flame was observed at the handle and cylinder position of doorset. The integrity failure was deemed to occur.



Issue Date: 2019-11-27

Intertek Report No.: 190920007SHF-001

This assembly therefore met the criteria of the test standards for integrity performance of 36 minutes.

### Insulation

Transmission of heat through the assembly during the fire resistance test of 36 minutes did not raise the average temperature on the unexposed surface by more than 140°C above its initial value, and did not raise the maximum temperature on the unexposed surface by more than 180°C above the initial mean unexposed face temperature. In addition, the transmission of heat through the assembly did not raise the maximum temperature of the unexposed surface of the frame by more than 360°C for 36 minutes.

The Performance criteria "insulation" shall automatically be assumed not to be satisfied when the "integrity" criterion ceases to be satisfied.

This assembly therefore met the criteria of the test standards for insulation performance of 36 minutes.

A full set of test data is included in Section 10, and photographs have been presented in Section 11.




### **TEST REPORT**

Issue Date: 2019-11-27

#### Intertek Report No.: 190920007SHF-001

#### **SECTION 6**

#### FIRE DOOR ASSEMBLY DRAWING



### Assembly Drawing of single leaf timber door with particle board core, model of MS-001A




### **TEST REPORT**

Issue Date: 2019-11-27

#### Intertek Report No.: 190920007SHF-001

#### **SECTION 7**

HARDWARE DRAWING




Installation instruction of door closer, model of D3023BW



### **TEST REPORT**

Issue Date: 2019-11-27

Intertek Report No.: 190920007SHF-001




Assembly drawing of Hinge, model of DDSS001-4×3×3.0mm-SUS201



Intertek Testing Services Shenzhen Ltd. Shanghai Fengxian Branch Plant 5, No. 6958 Daye Road, Fengxian District, Shanghai, China Tel: 021-61136116 Fax: 021-61189921 Website: www.intertek.com

Issue Date: 2019-11-27

Intertek Report No.: 190920007SHF-001








Issue Date: 2019-11-27

Intertek Report No.: 190920007SHF-001

#### **SECTION 8**

#### **TEST WALL CONSTRUCTION**



NOTE: TESTED DOOR MS-001A IS FOR THIS REPORT.




### **TEST REPORT**

Issue Date: 2019-11-27

Intertek Report No.: 190920007SHF-001

#### **SECTION 9**

**TEST MEASUREMENT DATA** 



**EXPOSED SIDE** 

Clearance dimension in mm at each position - the out-swing window													
Α	A B C D E F G H I J K L M N												
1.1	1.6	1.2	1.6	1.8	1.2	0.6	4.0	2.8	5.2	1.1	0.6	1.4	2.1

DO NOT SCALE


### DOOR ASSEMBLY INITIAL CLEARANCES



### **TEST REPORT**

Issue Date: 2019-11-27

Intertek Report No.: 190920007SHF-001



#### **UNEXPOSED SIDE**


### POSITON FOR MEASUREMENT OF HORIZONTAL DEFLECTION



### **TEST REPORT**

Issue Date: 2019-11-27

Intertek Report No.: 190920007SHF-001



#### **UNEXPOSED SIDE**

#### POSITON FOR MEASUREMENT OF UNEXPOSED TEMPERATURE



### **TEST REPORT**

Issue Date: 2019-11-27

Intertek Report No.: 190920007SHF-001

### **SECTION 10**

TEST DATA

Standards:	EN 1634-1:2014+A1:2018, Fire resistance and smoke control tests for door
	and shutter assemblies, openable windows and elements of building
	hardware – Part 1: Fire resistance test for door and shutter assemblies and
	openable windows
Procedure:	Part 1: Fire resistance test for door and shutter assemblies and openable

windows

Conditioning: According to EN1363-1, Section 8

### Equipment:

ITEM	ID
Vertical furnace	SH1097
Furnace pressure gauge	SH1097-15
Test Clock	SH1042
Furnace thermocouple	SH1097-4~6
Ambient temperature gauge	SH1097-11
Unexposed thermocouple	SH1097-12~14
Clearance Measurements	SH1057-1
Displacement Measurements	SH1163

According to EN 1363-1, Section 5.1
According to EN1363-1, Section 5.2
10~40°C according to EN 1363-1, Section 5.6
According to EN 1634-1, Section 6
According to EN 1634-1, Section 7
According to EN 1634-1, Section 9.1.1
According to EN 1634-1, Section 9.1.2
Length and width 30 mm, thickness $2.0 \pm 0.5$ mm, dry density 900
± 90 kg/m²
According to EN 1634-1, Section 9.2
According to EN 1634-1, Section 9.3
According to EN 1634-1, Section 10.1
According to EN 1634-1, Section 10.2



Issue Date: 2019-11-27

Intertek Report No.: 190920007SHF-001

### **Test Observations:**

Tir	ne	All observations are from the unexposed face unless noted otherwise.					
Mins	Secs	An observations are nom the unexposed face unless noted otherwise.					
00	00	Test started.					
01	30	Smoke issued from all edges of doorset.					
10	01	Smoke issued from the handle and cylinder position of doorset.					
24	10	Discoloration was observed at the handle and cylinder position of doorset.					
28	35	A cotton pad was applied on the cylinder position of door, and the pad was not ignited.					
34	53	Intermittent flame was observed at the handle and cylinder position of doorset and lasted for less than 10 seconds.					
36	04	Sustained flame was observed at the handle and cylinder position of doorset. The integrity failure was deemed to occur.					
36	32	Test was discontinued at the request of the client.					



Issue Date: 2019-11-27

Intertek Report No.: 190920007SHF-001

### Temperature Data:


Mean furnace temperature together with temperature-time relationship specified in the standard

Time Mins	Specified Furnace Temperature (°C)	Furnace Mean Temperature (°C)	Time Mins	Specified Furnace Temperature (°C)	Furnace Mean Temperature (°C)
0	20	22	19	774	801
1	349	105	20	781	806
2	445	286	21	789	815
3	502	490	22	796	823
4	544	563	23	802	830
5	576	617	24	809	837
6	603	652	25	815	843
7	626	679	26	820	850
8	645	702	27	826	856
9	663	720	28	832	861
10	678	733	29	837	868
11	693	746	30	842	873
12	705	760	31	847	879
13	717	768	32	851	884
14	728	766	33	856	889
15	739	773	34	860	895
16	748	779	35	865	903
17	757	785	36	869	907
18	766	793	/	/	/



Issue Date: 2019-11-27

Intertek Report No.: 190920007SHF-001



### Graph for mean furnace temperature and temperature-time curve specified in the standard



## TEST REPORT

Issue Date: 2019-11-27

Intertek Report No.: 190920007SHF-001

### **Unexposed surface temperatures**

Time Mins	T1 (°C)	T2 (°C)	ТЗ (°С)	Т4 (°С)	T5 (°C)	Mean Temperature (°C)
0	21	20	20	20	20	20
3	22	20	20	20	20	21
6	22	21	21	20	20	21
9	25	26	23	28	24	25
11	29	33	27	37	32	32
12	32	37	29	41	36	35
13	35	40	32	44	39	38
15	39	45	36	49	45	43
18	45	51	43	54	52	49
21	51	56	50	57	58	54
24	56	61	56	59	62	59
27	61	65	61	63	65	63
30	65	68	65	64	68	66
33	69	72	69	67	71	70
36	72	75	72	70	74	73

Time Mins	Т6 (°С)	T7 (°C)	Т8 (°С)	Т9 (°С)	T10 (°C)	T11 (°C)	T12 (°C)	T13 (°C)	T14 (°C)	T15 (°C)
0	20	20	20	21	20	19	19	19	19	19
3	20	20	21	22	20	19	19	20	19	19
6	20	21	22	23	20	19	19	21	20	19
9	28	28	26	25	26	19	19	21	20	19
12	41	40	35	31	37	19	20	21	20	19
15	51	49	44	39	45	19	20	21	21	19
18	59	55	50	46	51	19	21	21	21	19
21	65	60	57	53	56	19	22	22	22	19
24	68	63	60	59	60	19	23	22	22	20
27	71	67	64	63	62	19	24	23	23	20
30	73	69	67	68	65	19	25	24	23	20
33	75	72	72	72	68	20	26	24	25	20
36	78	75	75	75	71	20	29	25	26	20



Issue Date: 2019-11-27

Intertek Report No.: 190920007SHF-001

### Horizontal Deflection (Positive values indicate movement into the furnace)

Time Mins	D1 (mm)	D2 (mm)	D3 (mm)	D4 (mm)	D5 (mm)	D6 (mm)	D7 (mm)
0	0	0	0	0	0	0	0
10	0	-4	6	0	0	4	0
20	0	-3	3	0	0	4	1

### Door Closer Closing Force

Closing Force							
Highest gauge reading Distance Moment							
(N)	(m)	(N.m)					
42.6	1.01						
39.5	1.01	40.7					
38.7	1.01						




Intertek Report No.: 190920007SHF-001

### **TEST REPORT**

Issue Date: 2019-11-27

### Furnace pressure





Issue Date: 2019-11-27

Intertek Report No.: 190920007SHF-001

### SECTION 11 PHOTOGRAPHS



Fig. 1 Exposed Side Prior to the Fire Test



Fig. 2 Unexposed Side Prior to the Fire Test



Issue Date: 2019-11-27

Intertek Testing Services Shenzhen Ltd. Shanghai Fengxian Branch Plant 5, No. 6958 Daye Road, Fengxian District, Shanghai, China Tel: 021-61136116 Fax: 021-61189921 Website: www.intertek.com



Intertek Report No.: 190920007SHF-001

Fig. 3 Unexposed Side after 10 Minutes



Fig. 4 Unexposed Side after 28 Minutes



Issue Date: 2019-11-27

Intertek Testing Services Shenzhen Ltd. Shanghai Fengxian Branch Plant 5, No. 6958 Daye Road, Fengxian District, Shanghai, China Tel: 021-61136116 Fax: 021-61189921 Website: www.intertek.com



Fig. 5 Unexposed Side after 30 Minutes



Fig. 6 Unexposed Side after 34 Minutes

Intertek Report No.: 190920007SHF-001



Issue Date: 2019-11-27

Intertek Testing Services Shenzhen Ltd. Shanghai Fengxian Branch Plant 5, No. 6958 Daye Road, Fengxian District, Shanghai, China Tel: 021-61136116 Fax: 021-61189921 Website: www.intertek.com



### Intertek Report No.: 190920007SHF-001

Fig. 7 Unexposed Side after 36 Minutes



Fig. 8 Exposed Side after 36 Minutes



### **TEST REPORT**

Issue Date: 2019-11-27

Intertek Report No.: 190920007SHF-001

### SECTION 12

**REVISION LOG** 

<b>REVISION #</b>	DATE	PAGES	REVISION
0	2019-11-27	N/A	Original Report Issue